

# Car Credit Nation

WE DELIVER MORE THAN JUST CARS

## 2018 DODGE JOURNEY

Stock #: 21053R

Transmission: 6-Speed Automatic

VIN #: 3C4PDCEG0JT439181

ENGINE: 3.6 L/220L

INTERIOR:

DRIVE TRAIN: Front Wheel Drive

COLOR: Blood Orange Clear Coat

MILEAGE: 117628



### Tier 3

**PRICE:\* \$12,990**

**Financing As Low As:**

\$70 / week

\$995 / down



**Fuel Economy**

**CITY HWY**  
**17.0 25.0**

**SALES HOURS**  
**Mon-Fri 9am-6pm**  
**Sat- 9am-5pm**

**Dealer Contact Info**  
Phone - 540 323-7555  
Sales@carcreditnation.com

- » 3.16 Axle Ratio
- » High Performance Suspension
- » GVWR: 5,475 lbs
- » 50 State Emissions
- » Transmission w/AUTOSTICK Sequential Shift Control and Oil Cooler
- » Front-Wheel Drive
- » Engine Oil Cooler
- » 525CCA Maintenance-Free Battery w/Run Down Protection
- » 160 Amp Alternator
- » Towing Equipment -inc: Trailer Sway Control
- » Gas-Pressurized Shock Absorbers
- » Front And Rear Anti-Rolls
- » Hydraulic Power-Assist Speed-Sensing Steering
- » 20.5 Gal. Fuel Tank
- » Quasi-Dual Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- » Strut Front Suspension w/Coil Springs
- » Multi-Link Rear Suspension w/Coil Springs
- » 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs and Brake Assist
- » Tires: P225/55R19 BSW AS Touring
- » Steel Spare Wheel
- » Compact Spare Tire Stored Underbody w/Crankdown
- » Clearcoat Paint
- » Body-Colored Front Bumper w/Metal-Look Bumper Insert
- » Body-Colored Rear Bumper
- » Black Side Windows Trim
- » Body-Colored Door Handles
- » Body-Colored Power Heated Side Mirrors w/Manual Folding
- » Fixed Rear Window w/Fixed Interval Wiper and Defroster
- » Deep Tinted Glass
- » Speed Sensitive Variable Intermittent Wipers
- » Galvanized Steel/Aluminum/Composite Panels
- » Body-Colored Grille
- » Liftgate Rear Cargo Access
- » Auto On/Off Reflector Halogen Daytime Running Headlamps w/Delay-Off
- » Perimeter/Approach Lights
- » Front Fog Lamps
- » LED Brakelights
- » Graphic Equalizer
- » Integrated Roof Antenna
- » Streaming Audio
- » 368w Regular Amplifier
- » Uconnect w/Bluetooth Wireless Phone Connectivity
- » 1 LCD Monitor In The Front
- » 4-Way Passenger Seat -inc: Manual Recline and Fore/Aft Movement
- » 40-60 Folding Split-Bench Front Facing Manual Reclining Tilt ft.n Slide Fold Forward Seatback Rear Seat w/Manual Fore/Aft
- » Manual Tilt/Telescoping Steering Column
- » Fixed 50-50 Bench 3rd Row Seat Front, Manual Recline, Manual Fold Into Floor and 2 Fixed Head Restraints
- » Heated Leather/Metal-Look Steering Wheel
- » Illuminated Front Cupholder
- » Rear Cupholder
- » Compass
- » Valet Function
- » Cruise Control w/Steering Wheel Controls
- » HVAC -inc: Underseat Ducts, Auxiliary Rear Heater and Headliner/Pillar Ducts
- » Illuminated Locking Glove Box
- » Driver Foot Rest
- » Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and Chrome/Metal-Look Interior Accents
- » Full Cloth Headliner
- » Leatherette Door Trim Insert
- » Leather/Chrome Gear Shifter Material
- » Day-Night Auto-Dimming Rearview Mirror
- » Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- » Full Floor Console w/Covered Storage, Mini Overhead Console w/Storage, Conversation Mirror, 4 12V DC Power Outlets and 1 120V AC Power Outlet
- » Front And Rear Map Lights
- » Fade-To-Off Interior Lighting
- » Carpet Floor Trim

**Price and Payment Disclaimer** - The total sales price is \$12990.00. The displayed **amount financed** is the remainder of the sales price after a \$995 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 231 weekly payments and an interest rate of 9.9% APR per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

- » Cargo Area Concealed Storage
- » Cargo Net
- » Cargo Space Lights
- » Instrument Panel Bin, Interior Concealed Storage, Driver / Passenger And Rear Door Bins and 2nd Row Underseat Storage
- » Delayed Accessory Power
- » Driver Information Center
- » Redundant Digital Speedometer
- » Outside Temp Gauge
- » Digital/Analog Appearance
- » Manual Anti-Whiplash w/Tilt Front Head Restraints and Manual Adjustable Rear Head Restraints
- » Front Center Armrest and Rear Center Armrest
- » 1 Seatback Storage Pocket
- » Driver And Passenger Heated-Cushion, Driver And Passenger Heated-Seatback
- » Sentry Key Immobilizer
- » Perimeter Alarm
- » 4 12V DC Power Outlets
- » Air Filtration
- » 4 12V DC Power Outlets and 1 120V AC Power Outlet
- » Side Impact Beams
- » Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- » Tire Specific Low Tire Pressure Warning
- » Dual Stage Driver And Passenger Front Airbags
- » Airbag Occupancy Sensor
- » Driver Knee Airbag
- » Rear Child Safety Locks
- » Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point, Height Adjusters and Pretensioners
- » Curtain 1st, 2nd And 3rd Row Airbags

# BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

DODGE      JOURNEY      2018      3C4PDCEG0JT439181  
VEHICLE MAKE      MODEL      YEAR      VEHICLE IDENTIFICATION NUMBER(VIN)

## WARRANTIES FOR THIS VEHICLE:

### AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

### DEALER WARRANTY

- FULL WARRANTY.
- LIMITED WARRANTY. The dealer will pay 100 % of the labor and 100 % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

#### SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)  
ENGINE  
TRANSMISSION  
DIFFERENTIAL & TRANSFER CASE  
DRIVESHAFT & AXLES

#### DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST  
30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST  
30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST  
30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST  
30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

## NON-DEALER WARRANTIES FOR THIS VEHICLE:

- MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
- MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
- OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.

- SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's law may give you additional rights.

#### ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

**OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS.** For information on how to obtain a vehicle history report, visit [ftc.gov/usedcars](http://ftc.gov/usedcars). To check for open safety recalls, visit [safecar.gov](http://safecar.gov). You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

**SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.**

**Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español**

**Below is a list of some major defects that may occur in motor vehicles.**

**Frame & Body**

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

**Engine**

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

**Transmission & Drive Shaft**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

**Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

**Cooling System**

- Leakage including radiator
- Improperly functioning water pump

**Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

**Fuel System**

- Visible leakage

**Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

**Brake System**

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

**Steering System**

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

**Suspension System**

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

**Tires**

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

**Wheels**

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

**Exhaust System**

- Leakage
- Catalytic Converters

**Airbags**

---

CAR CREDIT NATION

-----  
DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

-----  
ADDRESS

Chris Maher Jr(540-323-7555)

Email: ChrisJr@carcreditnation.com

-----  
SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

-----  
CUSTOMERS SIGNATURE

DATE

---

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)