# **Car Credit Nation**

WE DELIVER MORE THAN JUST CARS

#### **2019 KIA OPTIMA**

Stock #: 21593

Transmission: 6-Speed Automatic

VIN #: 5XXGT4L32KG342389

ENGINE: 2.4 L, Theta II I4

INTERIOR: Black Cloth, cloth

**DRIVE TRAIN:** 

COLOR: Snow White Pearl

MILEAGE: 99483



## Tier 3

PRICE:\* \$14,490

Financing As Low As:

\$78 / week \$995 / down

- » ABS Brakes
- » Child Safety Door Locks
- » Cruise Control
- » Driver Airbag
- » Front Power Lumbar Support
- » Front Side Airbag
- » Passenger Airbag
- » Power Windows
- » Side Head Curtain Airbag
- » Telescopic Steering Column
- » Vehicle Anti-Theft



SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

**Dealer Contact Info** 

Phone - 540 323-7555 Sales@carcreditnation.com

**Price and Payment Disclaimer** - The total sales price is \$14490.00. The displayed **amount financed** is the remainder of the sales price after a \$995 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 234 weekly payments and an interest rate of 9.9% APR per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

## **BUYERS GUIDE**

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

KIAOPTIMA20195XXGT4L32KG342389VEHICLE MAKEMODELYEARVEHICLE IDENTIFICATION NUMBER(VIN)

#### **WARRANTIES FOR THIS VEHICLE:**

AS	IS-	NO	DEAL	_ER	WA	RRA	NTY	7

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

## DEALER WARRANTY

FULL WARRANTY.

**✓** 

LIMITED WARRANTY. The dealer will pay **100** % of the labor and **100** % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

#### **SYSTEMS COVERED:**

INTERNALLY LUBRICATED PARTS (ONLY)

**ENGINE** 

**TRANSMISSION** 

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

#### **DURATION:**

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

#### NON-DEALER WARRANTIES FOR THIS VEHICLE:

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
OTHER USED VEHICLE WARRANTY APPLIES.
Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.
SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, <i>implied</i> warranties under your state's law may give you additional rights.

#### ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

**OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS.** For information on how to obtain avehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

#### Below is a list of some major defects that may occur in motor vehicles.

#### Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

#### **Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

#### **Cooling System**

- Leakage including radiator
- Improperly functioning water pump

#### **Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

#### **Fuel System**

Visible leakage

#### **Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- · Heater & Deforester

#### **Brake System**

- Failure warning light broken
  Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering SystemToo much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jamsFront wheels aligned improperly (DOT
- Power unit belts cracked or slippingPower unit fluid level improper

#### Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
  Shock absorber mounting loose
  Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

#### Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

#### Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

#### **Exhaust System**

- LeakageCatalytic Converters

#### Airbags

### CAR CREDIT NATION DEALER 1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602 **ADDRESS** Chris Maher Jr(540-323-7555) Email: ChrisJr@carcreditnation.com SEE FOR COMPLAINTS I hereby acknowledge notice of the Buyers Guide at the closing of this sale. **CUSTOMERS SIGNATURE** DATE