Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2018 CHEVROLET MALIBU

Stock #: 21864

Transmission: 6-Speed Automatic

VIN #: 1G1ZB5ST8JF225263

ENGINE: 1.5 L, ECOTEC 14

INTERIOR: Dark Atmosphere/Medium Ash Gray

DRIVE TRAIN:

COLOR: BLUE

MILEAGE: 58637



Tier 4

PRICE:* \$16,990

Financing As Low As:

\$79 / week \$2,495 / down



SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

Dealer Contact Info

Phone - 540 323-7555 Sales@carcreditnation.com

» ABS Brakes

- » Air Conditioning
- » Alloy Wheels
- » AM/FM Radio
- » Automatic Headlights
- » Cargo Net
- » Child Safety Door Locks
- » Chrome Wheels
- » Daytime Running Lights
- » Deep Tinted Glass
- » Driver Airbag
- » Electrochromic Exterior Rearview Mirror
- » Front Side Airbag
- » Front Side Airbag with Head Protection
- » Full Size Spare Tire
- » Genuine Wood Trim
- » Keyless Entry
- » Leather Seat
- » Leather Steering Wheel
- » Passenger Airbag
- » Power Door Locks
- » Power Trunk Lid
- » Power Windows
- » Rear Window Defogger
- » Remote Ignition
- » Run Flat Tires
- » Second Row Side Airbag
- » Sliding Rear Pickup Truck Window
- » Steel Wheels
- » Steering Wheel Mounted Controls
- » Tachometer
- » Telescopic Steering Column
- » Tilt Steering Column
- » Tire Pressure Monitor
- » Traction Control
- » Trip Computer
- » Vehicle Anti-Theft
- » Vehicle Stability Control System
- » Voice Activated Telephone

Price and Payment Disclaimer - The total sales price is \$16990.00. The displayed **amount financed** is the remainder of the sales price after a \$2495 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 252 weekly payments and an interest rate of 9.9% APR per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

CHEVROLET MALIBU

2018

1G1ZB5ST8|F225263

VEHICLE MAKE

MODEL

YEAR

VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:



THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

DEALER WARRANTY

FULL WARRANTY.

✓

LIMITED WARRANTY. The dealer will pay **100** % of the labor and **100** % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3.000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

NON-DEALER WARRANTIES FOR THIS VEHICLE:

warranties under your state's law may give you additional rights.

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
OTHER USED VEHICLE WARRANTY APPLIES.
Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.
SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage,

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain avehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- · Heater & Deforester

Brake System

- Failure warning light broken
 Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering SystemToo much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jamsFront wheels aligned improperly (DOT
- Power unit belts cracked or slippingPower unit fluid level improper

Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected
- · Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- LeakageCatalytic Converters

Airbags

CAR CREDIT NATION DEALER 1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602 **ADDRESS** Jacob Maher(540-323-7555) Email: Jacob@carcreditnation.com SEE FOR COMPLAINTS I hereby acknowledge notice of the Buyers Guide at the closing of this sale. **CUSTOMERS SIGNATURE** DATE