

# Car Credit Nation

WE DELIVER MORE THAN JUST CARS

## 2010 DODGE GRAND CARAVAN

Stock #: 21058R

Transmission: 6-Speed Automatic

VIN #: 2D4RN5D16AR156899

ENGINE: 3.8L/231L

INTERIOR:

DRIVE TRAIN: Front Wheel Drive

COLOR: Inferno Red Crystal Pearlcoat

MILEAGE: 141666



### Tier 1

**PRICE:\* \$7,490**

**Financing As Low As:**

\$65 / week

\$995 / down



### SALES HOURS

**Mon-Fri 9am-6pm**

**Sat- 9am-5pm**

### Dealer Contact Info

Phone - 540 323-7555

Sales@carcreditnation.com

- » 3.8L OHV V6 engine (REQ: NAS Emissions)
- » Front wheel drive
- » 600-amp maintenance-free battery
- » 160-amp alternator
- » Pwr rack & pinion steering
- » 4-wheel disc brakes
- » Yokohama tires
- » Compact spare tire
- » Black side rails w/crossbars
- » Body-color fascias
- » Rear scuff pad
- » Front air dam
- » Bright bodyside moldings
- » Belt moldings
- » Black/bright grille
- » Halogen headlamps
- » Fog lamps
- » Fold-away heated pwr mirrors
- » Body-color mirrors
- » Sunscreen glass
- » Rear window wiper/washer
- » Bright license plate brow
- » Body-color door handles
- » (6) speakers
- » Fixed long mast antenna
- » Driver manual lumbar adjust
- » Stain repel seat fabric
- » Floor console w/cupholder
- » Carpet flooring
- » Body-color sill applique
- » Leather-wrapped steering wheel
- » Tilt steering wheel
- » Steering wheel mounted audio controls
- » Instrument panel w/blackwood & satin silver bezel
- » White face instrument cluster w/tachometer
- » Lower instrument panel cubby bin
- » Trip computer w/temp, compass
- » Pwr adjustable pedals
- » Tip start
- » Universal garage door opener
- » Speed control
- » Rear window defroster
- » Dual glove boxes
- » Blackwood door trim panel
- » Driver door sill storage bin
- » Illuminated front door storage
- » Overhead console
- » Overhead storage bins
- » Rear overhead console system
- » Observation mirror
- » Dual sun visors w/illuminated mirrors
- » Assist handles
- » Door courtesy lamps
- » Swiveling rear courtesy/reading lamps
- » Cupholders w/overhead illumination
- » Illuminated entry
- » Overhead ambient surround lighting
- » Liftgate flood lamp
- » Leather-wrapped shift knob
- » Rear seatback grocery bag hooks
- » LH rear quarter storage bin
- » 4-wheel anti-lock brakes
- » Brake assist
- » Brake/park interlock
- » Electronic stability control
- » Advanced multi-stage front air bags
- » Side curtain air bags for all rows
- » LATCH ready child seat anchor system
- » Rear door child safety locks
- » Tire pressure monitor
- » Dual note electric horn

**Price and Payment Disclaimer** - The total sales price is \$7490.00. The displayed **amount financed** is the remainder of the sales price after a \$995 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 115 weekly payments and an interest rate of 9.9% APR per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

# BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

DODGE      GRAND CARAVAN      2010      2D4RN5D16AR156899  
VEHICLE MAKE      MODEL      YEAR      VEHICLE IDENTIFICATION NUMBER(VIN)

## WARRANTIES FOR THIS VEHICLE:

### AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

### DEALER WARRANTY

FULL WARRANTY.

LIMITED WARRANTY. The dealer will pay 100 % of the labor and 100 % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

#### SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

#### DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

## NON-DEALER WARRANTIES FOR THIS VEHICLE:

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.

MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.

OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.

SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's law may give you additional rights.

#### ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

**OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS.** For information on how to obtain a vehicle history report, visit [ftc.gov/usedcars](http://ftc.gov/usedcars). To check for open safety recalls, visit [safecar.gov](http://safecar.gov). You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

**SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.**

**Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español**

**Below is a list of some major defects that may occur in motor vehicles.**

**Frame & Body**

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

**Engine**

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

**Transmission & Drive Shaft**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

**Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

**Cooling System**

- Leakage including radiator
- Improperly functioning water pump

**Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

**Fuel System**

- Visible leakage

**Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

**Brake System**

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

**Steering System**

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

**Suspension System**

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

**Tires**

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

**Wheels**

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

**Exhaust System**

- Leakage
- Catalytic Converters

**Airbags**

---

CAR CREDIT NATION

-----  
DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

-----  
ADDRESS

Chris Maher Jr(540-323-7555)

Email: ChrisJr@carcreditnation.com

-----  
SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

-----  
CUSTOMERS SIGNATURE

DATE

---

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)